U.S. Senate Desk Description and Condition Report

Desk No: 66.00005.000

Paper Label No.(on shelf bottom): 5 Painted No. (on bottom): N/A

Other identifying labels or marks (specify location): Stretcher: 5, 5, V; Top: 5; Drawer Bottom: outside - No. 6, 5 (pencil), remnant of paper label; inside - 5, 5 (both pencil), V; Drawer Back: 5; Inside Case Back: 99 (pencil); Bottom of Shelf: 5 (paper), 5 (chalk), No.?; Drawer Blade: 5, 5 (both pencil), 6

Description of Desk

Dimensions (in inches)

	Overall	Orig. Desk*	Case	Shelf
Height	34 1/2	32 5/16		
Width (front)	27 7/8	26 3/16	25 1/2	
Width (rear)	25 5/8	24 1/16	23 1/2	
Depth	19 3/4	20	19 3/16	9

^{*} Note: Dimensions do not include "booster" blocks added to feet or writing top.

Woods

		THE RESERVE OF THE PARTY OF THE	
Primary:	Mahogany	Character of case mahogany:	Plain 🗆
	Mahogany veneer ■		Ribbon 🗆
Other Wo	Rosewood veneer		Mottled
			Crotch
			Other

Secondary:

Element	Pine	Ash	Poplar	Mahog	Other
Drawer Sides				1	
Drawer Bottom			1		
Drawer Back			1		
Case Interior	1	1			
Drawer Front	1		No.		HERE ILL -

Construction Details

Leg:			House English		
	Wood Type	rosewood crossband	other	n d cross	o sband
	mahog. veneer	/	1		
	solid mahogany				
	other:		4		
Foot construc	tion: 1-part □	Cockbead width o	n bottom of	drawer fro	nt:
root constitue	2-part ■	Fig. 5 and the Control of Wilder		N	arrow
	5-part 🗆			Full	width 🗆
	Other:	5 55 5 15 5 NASSESTIMATE AT			
	* ******	Opening in origina	top for ink	well:	Yes ■
Double bead	on edge of leg:				No □
	Leg Thickness: 1 3/16 "	Roundels:	Single pie	ce ("yo-yo	" form)■
Shape of cros	ss-stretcher edges:			Applied	boss 🗆
	Rounded □	1			W.T.
	Rectangular	Inset distance of s	ingle bead	on desk ba	ck
Spindle type:	Thick Thin Other	1		Sid	e: 1 1/4"
Number	1 3 6	i		Т	op: 7/8"
Number				Bo	ttom: 1"
Joinery of low	er drawer blade to case sides:				
	single dovetail	No. of Glue Bloc	ks Case	Stretch'r	Shelf
	2 dovetails □	Original/Old	0		
	3 dovetails □	New/Recent		2	2
	lap joint □	Missing			
	other: single dovetail ,1 lap joint				
		Case built-out for	drawer:		Yes
					No 🗆

Condition of Desk

Structure

Previous breaks in structural eleme	ents: Yes ■	Wear on Feet	Extreme M	oderate	Minor
(show on schematic)	No □	Front	1		
		Rear			1
Current split or broken elements: (show on schematic)	Yes ■	h			
(Show on schematic)	No □	Number of loose	spindles:	165	No: 0
Other loose or damaged joinery: (describe in narrative)	Yes □	Number of replace	and the state of t		No: 7
**************************************	No ■	P			V. 194
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		Replaced venee		anding:	Yes
Damage to drawer front:	Extreme	(show on scher	natic)		
	Moderate ■		2 1222		No 🗆
44 40	Minor 🗆	Missing veneers		ding:	Yes 🗆
Drawer lock: relocated on face	Yes ■	(show on scher	natic)		No 🔳
Drawer lock: resized on inside	Yes■	Delaminated/loo	se veneers &		Yes
Cockbead on drawer front:	Damaged	cross-banding:			
(show on schematic)	Damayeu -	(show on scher	natic)		No 🗆
	Missing □	Shelf supports:	1 141 111	Origi	nal/old □
	Loose 🗆			New	recent
Re	placements			N	Missing [
Replaced drawer-side runners:	Yes □	Shelf molding ap	pplied:		Yes 🗆
(f = 0) = (0) =	No 🖩	SMOOTHER GRAN			No
Replaced case-side runners:	Yes □	Spindle support	hoord in cook		Voc
	No ■	Spindle support	board in case:		Yes
		-			No 🗆
Drawer bottom pieced-out at back	edge: Yes 🗆				
	No ■				

Finish

Age	Excellent	Good	Fair	Poor	ĺ
New		100	1		į
Old					
Unk.					

Note: Describe finish problems in narrative.

Hardware/Attachments

Item	Mismatch	Missing	Damaged
Knob (L)	1		
Knob (R)		1	1167

Toe cap size:

Right toe: 4

Left toe: 4