



Front View

Rear View



Loose/broken/delaminated  
Damage/wear/hole



Previous repair  
Replaced piece

Missing  
Spindles not original to desk

Add-ons  
Inscriptions

Right Side

Left Side



*Note: No cross-banding on pedestal legs*


■ Loose/broken/delaminated  
■ Damage/wear/hole

■ Previous repair  
■ Replaced piece

■ Missing  
■ Spindles not original to desk

■ Add-ons  
■ Inscriptions


Top




 Loose/broken/delaminated


 Damage/wear/hole

 Previous repair

 Replaced piece


 Missing

 Spindles not original to desk


 Add-ons



 Inscriptions



Bottom







Bottom



 Loose/broken/delaminated  
 Damage/wear/hole

 Previous repair  
 Replaced piece


 Missing  
 Spindles not original to desk



 Add-ons  
 Inscriptions



Drawer Front, Outer Surface





Rear Surface of Drawer Front



 Loose/broken/delaminated  
 Damage/wear/hole



 Previous repair  
 Replaced piece

 Missing  
 Spindles not original to desk

 Add-ons  
 Inscriptions

Inside Surface of Left Drawer Side

Inside Surface of Right Drawer Side



■ Loose/broken/delaminated  
■ Damage/wear/hole

■ Previous repair  
■ Replaced piece


■ Missing  
■ Spindles not original to desk



■ Add-ons  
■ Inscriptions

Rear Surface of Drawer Back





Front Surface of Drawer Back



 Loose/broken/delaminated  
 Damage/wear/hole



 Previous repair  
 Replaced piece

 Missing  
 Spindles not original to desk

 Add-ons  
 Inscriptions

Upper Surface of Drawer Bottom

Lower Surface of Drawer Bottom



Loose/broken/delaminated  
Damage/wear/hole

Previous repair  
Replaced piece


Missing  
Spindles not original to desk



Add-ons  
Inscriptions







Outside Surface, Right Drawer Side



Outside Surface, Left Drawer Side



 Loose/broken/delaminated  
 Damage/wear/hole

 Previous repair  
 Replaced piece

 Missing  
 Spindles not original to desk

 Add-ons  
 Inscriptions