U.S. Senate Desk Description and Condition Report

Desk No: 66.00063.000

Paper Label No.(on shelf bottom): 83

Painted No. (on bottom): N/A

Other identifying labels or marks (specify location): Stretcher: 83, 85, LXIII; Top: 83, 83, 58;

Drawer back: 83

Description of Desk

Dimensions (in inches)

	Overall	Orig. Desk*	Case	Shelf
Height	35 11/16	32 3/8		
Width (front)	27 7/16	26 9/16	25 3/4	
Width (rear)	26 5/8	25 5/8	25 1/8	
Depth	20 3/16	20	19 1/8	9 7/8

^{*} Note: Dimensions do not include "booster" blocks added to feet or writing top.

Woods

Plain C	Character of case mahogany:	ry: Mahogany ■	
Ribbon	1) sa 1,556	Mahogany veneer	
Mottled □		Rosewood veneer Other Wood (specify):	
Crotch C			
Other C			

Secondary:

Element	Pine	Ash	Poplar	Mahog	Other
Drawer Sides			1		-1/68K-1955
Drawer Bottom			/		
Drawer Back			1		
Case Interior	1				
Drawer Front	1				***************************************

Case built-out for drawer:

Yes

No I

Condition of Desk

Structure

Previous breaks in structural element	ents: Yes	Wear on Feet	Extreme	Moderate	Minor	
(show on schematic)	No ■	Front	1			
		Rear		1	1	
Current split or broken elements: (show on schematic)	Yes ■	Number of loose spindles:			- /	
(onow on continuity)	No □	Number of loose	эршиез.		No: 0	
Other loose or damaged joinery: (describe in narrative)	Yes 🗆	Number of repla		98:	No: 2	
11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	No ■					
		Replaced veneers and cross-bandi (show on schematic)		ss-banding:	ng: Yes ■	
Damage to drawer fronts:	Extreme	(snow on schei	mauc)		No 🗆	
	Moderate ■				140 🗆	
	Minor 🗆	Missing veneers and cross-banding			Yes ■	
Drawer lock: relocated on face	(show on schematic)					
Drawer lock: resized on inside Yes		Delaminated/loo	se veneers	8.	Yes 🗆	
		cross-banding:				
Cockbead on drawer front: (show on schematic)	Damaged	(show on sche	matic)	(2 18 19—11 = 11	No ■	
	Missing	Shelf supports:	*******	Orig	inal/old □	
	Loose 🗆			New	/recent ■	
Re	eplacements				Missing 🗆	
Replaced drawer-side runners:	Yes 🗆	Shelf molding applied:			Yes □	
A TOTAL WELLING LAND	No ■	# # # # # # # # # # # # # # # # # # #			No ■	
Depleted and cide suppose	V []		300			
Replaced case-side runners:	Yes □	Dowel support to	ooard in cas	se:	Yes □	
	No ■		HDOM I	X 6 = 0	No ■	
Drawer bottom pieced-out at back	edge: Yes □					

No 🔳

Finish

Age	Excellent	Good	Fair	Poor
New		Average and		
Old				
Unk.				1

Note: Describe finish problems in narrative.

Hardware/Attachments

Item	Mismatch	Missing	Damageo
Knob (L)			
Knob (R)			1
Toe cap size	9:	R	ight toe:

regit too.

Left toe: 9