United States Senate Desk

Desk # 97

Front View

Add-on writing top not shown

Rear View





- Loose/broken/delaminated
- Damage/wear/hole
- Previous repair
- Replaced piece
- Missing
- Spindles not original to desk
- Add-ons
- Inscriptions

United States Senate Desk

Desk # 97

Right Side

Left Side

← Add-on writing top not shown →



N.B. No veneer or cross banding →

N.B. - Feet:
① Single slab construction →
② No pads



Loose/broken/delaminated
Damage/wear/hole
Previous repair
Replaced piece
Missing
Spindles not original to desk
Add-ons
Inscriptions

United States Senate Desk

Desk # 97

Top



Top view n/a

- Loose/broken/delaminated
- Damage/wear/hole
- Previous repair
- Replaced piece
- Missing
- Spindles not original to desk
- Add-ons
- Inscriptions

United States Senate Desk

Desk # 97

Bottom

Note case construction



Bottom



Loose/broken/delaminated

Damage/wear/hole

Previous repair

Replaced piece

Missing

Spindles not original to desk

Add-ons

Inscriptions

United States Senate Desk

Desk # 97

Drawer Front, Outer Surface



Rear Surface of Drawer Front



Loose/broken/delaminated

Damage/wear/hole

Previous repair

Replaced piece

Missing

Spindles not original to desk

Add-ons

Inscriptions

United States Senate Desk

Desk # 97

Inside Surface of Left Drawer Side



Inside Surface of Right Drawer Side



- Loose/broken/delaminated
- Damage/wear/hole
- Previous repair
- Replaced piece
- Missing
- Spindles not original to desk
- Add-ons
- Inscriptions

United States Senate Desk

Desk # 97

Rear Surface of Drawer Back



N.B. - Plywood bottom bagged

Front Surface of Drawer Back



Loose/broken/delaminated

Damage/wear/hole

Previous repair

Replaced piece

Missing

Spindles not original to desk

Add-ons

Inscriptions

United States Senate Desk

Desk # 97

Upper Surface of Drawer Bottom



Lower Surface of Drawer Bottom



- Loose/broken/delaminated
- Damage/wear/hole
- Previous repair
- Replaced piece
- Missing
- Spindles not original to desk
- Add-ons
- Inscriptions

United States Senate Desk

Desk # 97

Outside Surface, Right Drawer Side

Outside Surface, Left Drawer Side



- Loose/broken/delaminated
- Damage/wear/hole
- Previous repair
- Replaced piece
- Missing
- Spindles not original to desk
- Add-ons
- Inscriptions